

Safety Organisation



Pending accident DAR cases as on 01.03.2024

S. N.	Date	Description	Cause	Staff held responsible	Status of action initiated
AJMER DIVISION					
1	25.12.23	ECR of Train 12987/88 (Ajmer – Sealdah) was stabled at Pit line No. 8 for Primary maintenance at 04:00 Hrs on 25.12.23. Rake of ECR rolled down towards Ladpura end at 07:45 Hrs and dashed to dead end of shunting neck and 04 coaches derailed.	Load not secured properly.	Primary:- 1. Sanjay Palariya/Shunting Jamadar	Issue SF-11 on 16.02.2024. Issue Warning
				2. Ganesh Ram Meena/PM	Issue SF-11 on 16.02.2024
				3. Gopal Kumawat/PP	Issue SF-11 on 16.02.2024
				4. Narendra Kumar Jangid/MCM	Issue SF-11 on 24.01.2024
				5. Shelendra Kumar Kothari/MCM	Issue SF-11 on 24.01.2024
				Secondary:- 1. Nand Kumar Sharma/SSE/C&W	Issue SF-11 on 25.01.2024
				2. Rajendra Kumar Yadav/Yard Master	No CS. Issue Warning by Sr.DOM/All
Primary:- 1. Sanjay Palariya/Shunting Jamadar	Issue SF-11 on 16.02.2024. Issue Warning				
BIKANER DIVISION					
1	16.11.23	Train No DN/Electric Loco departed from CUR at 04/37 & arrived at HYL on 05/18. Due to reversal of BVZI of Train No DN GPHK (stabled in L.No.3) LP received T-806 and started shunting. while entering in line no 3 (from CUR side), due to foggy weather visibility was not cleared resulting engine dashed with BVZI no.86101285188/ECR and two wheels (rear wheel of rear trolley load side) of BVZI got derailed.	Negligence by LP/ALP and shunting staff during attaching the Loco to the brake van.	Primary 1.Puneet Kumar LP/HSR.	SF5 served on 18.12.2023
				2.Deepak Kumar ALP/HSR	SF-5 served on 18.12.2023
				3.Dinesh Kumar swami TM/CUR	.SF-5 served on 07.12.23
				4.Rajendra Kumar Points Man HYL	SF 5 Served on 07.12.23
				Secondary-NIL Blameworthy-NIL	
JAIPUR DIVISION					
1	17.02.24	LP of Down goods E/BOXNHL DP No. 41828 WAG9HC/ VTA Load 1/58, 1250 T, overshoot intermediate starter signal S-63 (MTJ Side) of down line no 1 by 35.95 metres at 5.46 hrs on dated 17.02.2024 in AWR yard.	Negligence of crew	Pending	Pending

JODHPUR DIVISION

1	05.02.24	Loco pilot of train no. 14704 Down Exp. has to stop his train at starter signal no. 31. Loco pilot can't stop train at S-31 and passed it by approximate 2 to 3 meters resulting fly back of Home Signal no S-48 of AQG taken off for train no. 20492 Down (SBI-JSM).	Negligence of Loco pilot and Assistant Loco Pilot of train no.. 14704.	Primary:- 1. Shyam Sundar Swami/LPM/BKN	Pending
				Primary:- 2.Sh. Madan Lal/ LPM/BKN	Pending
				Blameworthy:- 1.Sh. Yad Ram/CLI/CUR	Pending

**Pending accident DAR cases as 01.03.2024
(Other train accident)**

S. N.	Date	Station/Block Section	Brief	Prima Facie Cause
AJMER				
			NIL	
BIKANER				
			NIL	
			JAIPUR	
-	-	-	-	-
JODHPUR				
-	-	-	-	-