

Safety Organisation



Pending accident DAR cases as on 18.06.2024

S. N.	Date	Description	Cause	Staff held responsible	Status of action initiated
AJMER DIVISION					
1	18/03/2024 at 01:00 Hrs.	Train no. 12548 DN (Sabarmati BG - Agra Cantt) Express side collided with Down goods train No. LCTS/MBV (Clinker). As a result, train engine and its adjacent four coaches (1SLRD & 3 GS) derailed.	Crew of T.No.12548 passed Home Signal S/5 at danger and side collision to Goods train.	Primary:- 1.Nanag Ram LP	SF-5 issued on 30.4.2024
				2.Suwa Lal ALP	SF-5 issued on 29.04.2024
				Secondary:-	
				1.Sumer Singh CLI	SF-11 issued 30.4.2024.
				2.Usman Khan CLI	SF-11 issued 30.4.2024.
				2.Dalu Ram TM Jaipur	SF-11 Issued-April-24
BIKANER DIVISION					
JAIPUR DIVISION					
JODHPUR DIVISION					
1	05.02.2024 11:55	Loco pilot of train no. 14704 Down Exp. has to stop his train at starter signal no. 31. Loco pilot can't stop train at S-31 and passed it by approximate 2 to 3 meters resulting fly back of Home Signal no S-48 of AQG taken off for train no. 20492 Down (SBI-JSM).	Negligence of Loco pilot and Assistant Loco Pilot of train no. 14704.	Primary:- 1. Shyam Sundar Swami/LPM/BKN	SF-5 issued on 27.02.24
				Primary:- 2.Sh. Madan Lal/ LPM/BKN	SF-5 Issued on 27.02.24

Pending accident DAR cases as 18.06.2024
(Other train accident)

S. N.	Date	Station/Block Section	Brief	Prima Facie Cause
AJMER				
			NIL	
BIKANER				
			JAIPUR	
JODHPUR				